

Network:

Device-1: Qualcomm Atheros QCA9565 / AR9565 Wireless Network Adapter
driver: ath9k

IF: wlp1s0 **state:** up **mac:** a4:fc:77:7e:fd:75

Device-2: Realtek RTL810xE PCI Express Fast Ethernet **driver:** r8169

IF: enp2s0 **state:** down **mac:** d0:94:66:b1:3c:bd

Device-3: Qualcomm Atheros **type:** USB **driver:** btusb

```
2022-03-08 18:08:32 upgrade linux-generic-hwe-20.04:amd64 5.13.0.30.33~20.04.17 5.13.0.35.40~20.04.20
2022-03-08 18:08:32 upgrade linux-image-generic-hwe-20.04:amd64 5.13.0.30.33~20.04.17 5.13.0.35.40~20.04.20
2022-03-08 18:08:36 upgrade linux-headers-generic-hwe-20.04:amd64 5.13.0.30.33~20.04.17 5.13.0.35.40~20.04.20
2022-03-08 18:08:36 upgrade linux-libc-dev:amd64 5.4.0-100.113 5.4.0-104.118
```